Hamakua Police Station & CCC CRIFU

## LARGE CAPACITY CESSPOOL (LESS THAN 1000 GPD) BACKFILLING FINAL COMPLETION REPORT Wastewater Branch, Dept. of Health, State of Hawai'i

ackfilling contractor. <u>Ludwig Construction, Inc</u>
low was it compacted? Water and tamp with backhoe, last 3 feet with sted type compactor,
Vas the cesspool completely backfilled?      ✓□ Yes    □ No
Jale of Backfilling:8/6/06Type of backfil material:6* minus surge rock
Nas groundwater encountered? ☐ Yes ✔☐ No
sob's Pumping Service and disposed of at the Parker Ranch Sewer Treatment Plant
Was studge/sediment or liquid taken or disposed of?Yes. All studge and liquid was pumped out by
Diameter(s): 6' Depth(s): 17'
Number of cesspools, and numbering if any: 1
TMK: (3)4-5-06:003
Project Address:45 <u>-3384 Mamane St., Honokaa, Hamakua, Hawaii</u> 96727
New CITHERNIA

Please provide:

- Pictures: Attach photos of the large capacity cesspool from step-back distances of approximately 8 feet and 20 feet.
- Copy of this report to: LCC Project Coordinator EPA Ground Water Office (WTR-9) 75 Hawthorne Street San Francisco, CA 94105

Page 1 of 4

## LARGE CAPACITY CESSPOOL BACKFILLING FINAL COMPLETION REPORT (Continuation)

The backfilling work and the final completion report have been performed and completed under my supervision and the work was properly completed:

Phone: (808) 521-3051	Address: 841 Bishop Street Suite 1900, Honoluly, HI 96813	Company: _M & E Pacific, Inc.	Date: 4/7/07	Signed:	Printed Name: Martin Nakasone	전 Professional Engineer	expension and the work was properly completed;
Fax: (808) 524-0246	3813		(	*	- 3	Include P.E. Stamp:	\
		(	W. U.S.F.	No. 8701-C /*/	ENGINEER CO		

FOR OFFICIAL USE ONLY - DO NOT WRITE BELOW THIS LINE

IWS file no:

Date sent:

Date received:




Photo 2-4/3/2007 - Post (Finish) Condition 20 feet away from cesspool location.



Photo 1-4/3/2007 - Post (Finish) Condition 8 feet away from cesspool location.